



Pavilion front elevation



Pavilion rear elevation




Crack in parge coat where concrete deck meets concrete block wall - typical at perimeter



Missing stones at column



Cracks in concrete deck



Wood stairs



Pavement deterioration



Pavement deterioration



Pond dam



Entrance monument and guard house



Mortar deterioration



Monument wall deterioration




Playground equipment



Pond overview



Erosion at pond



Pond erosion, wood retaining wall and wood bridges



Erosion near pavilion



Tennis courts in good condition



Tennis court fence



Minor crack in pool deck



Pool cover



Rusted metal door - typical of all metal doors



Fiberglass pool coating and minor tile deterioration



Pool house interior with furniture



Bollard light



Light post and fixtures



Pool filters